



Boring: 01

X:
 Y:
 Datum: 4-11-2009
 GWS: 200



Opmerking:



Boring: 02

X:
 Y:
 Datum: 4-11-2009
 GWS: 200



Opmerking:



Boring: 03

X:
 Y:
 Datum: 4-11-2009
 GWS: 200



Opmerking:



Boring: 04

X:
 Y:
 Datum: 4-11-2009
 GWS: 200



Opmerking:



Boring: 04A

X:
 Y:
 Datum: 4-11-2009
 GWS:



Opmerking:



Boring: 04B

X:
 Y:
 Datum: 4-11-2009
 GWS:



Opmerking:



Boring: 401

X:
 Y:
 Datum: 3-11-2009
 GWS: 150



Opmerking:



Boring: 402

X:
 Y:
 Datum: 3-11-2009
 GWS: 200


Opmerking:



Boring: 403

X:
 Y:
 Datum: 3-11-2009
 GWS: 200


Opmerking:



Boring: 404

X:
 Y:
 Datum: 3-11-2009
 GWS: 200



Opmerking:



Boring: O100

X:
 Y:
 Datum: 28-10-2009
 GWS: 160



Opmerking:



Boring: O30

X:
 Y:
 Datum: 28-10-2009
 GWS: 200



Opmerking:



Boring: O40

X:
 Y:
 Datum: 28-10-2009
 GWS: 200



Opmerking:



Boring: O80

X:
 Y:
 Datum: 28-10-2009
 GWS: 150


Opmerking:



Boring: O90

X:
 Y:
 Datum: 28-10-2009
 GWS: 150


Opmerking:



Boring: O1M

X:
 Y:
 Datum: 3-11-2009
 GWS: 200



Opmerking:



Boring: O2M

X:
 Y:
 Datum: 3-11-2009
 GWS: 180


Opmerking:



Boring: O5M

X:
 Y:
 Datum: 3-11-2009
 GWS: 100




Opmerking:



Boring: O6M

X:
 Y:
 Datum: 3-11-2009
 GWS: 150


Opmerking:



Boring: O7M

X:
 Y:
 Datum: 3-11-2009
 GWS: 150


Opmerking:



Boring: W01

X:
 Y:
 Datum: 28-10-2009
 GWS: 250

Opmerking:



Boring: W02

X:
 Y:
 Datum: 28-10-2009
 GWS: 150

Opmerking:

